

9 June 2026



Nicole Brewer
Department of Planning, Housing and Infrastructure
The Planning Secretary
GPO Box 39
Sydney NSW 2001

Dear Nicole,

Subject: Independent Environmental Audit - Uungula Wind Farm SSD-6687

Please find attached the Independent Environmental Audit Report for the Uungula Wind Farm (UWF), prepared by Healthy Buildings International Pty Ltd, for the Secretary's review and acceptance. The audit period covered by the report is 18 November 2025 to 13 May 2026.

The audit found:

- 2 non-compliances, both self-reported within the audit period, and
- 1 opportunity for improvement

The audit found a high level of compliance with the project approval and associated post-approval documents. The Proponent's Response to Audit Findings is attached to this letter.

If you require any additional information or would like to further discuss this matter further, please contact Sanjay Goel on 0466 947 758 or Sanjay.goel@squadronenergy.com.

Yours sincerely,

A handwritten signature in black ink that reads "Sanjay Goel".

Sanjay Goel

Project Director

For and on behalf of Uungula Wind Farm Pty Ltd (ABN 68 143 399 295)

Attachment A – Proponent Response to Audit Findings

+61 8 6460 4949
info@squadronenergy.com
squadronenergy.com

Suite 1.01, Lvl 1
17 Moore St,
Canberra, ACT
2601 Australia

PO Box 3155
Broadway Nedlands
WA 6009 Australia

ABN 13 615 221 559
ACN 666 548 394
**Squadron Energy Services
Pty Ltd**

Incorporating the business of
CWP Renewables Pty Ltd

Finding ID	Compliance Requirement	Audit Recommendation	UWF Response	Proposed Due Date
NC-1	Condition A2(b)	SQE to maintain ongoing consultation with all relevant parties and continue submitting letter reports every two months to DPHI via the Major Projects Portal as per DPHI written direction.	Noted. UWF will continue to maintain ongoing consultation with all relevant parties and comply with reporting requirements.	Ongoing
NC-2	Condition B35	<p>Actions undertaken by SQE:</p> <p>Submit all outstanding notifications to CASA, Airservices Australia, and the RAAF for any meteorological monitoring masts where pre-construction notification requirements were not previously fulfilled, ensuring these are not already covered by post-construction notifications;</p> <p>Conduct a detailed internal investigation to determine the root cause of the notification oversight. The investigation will review project records, communication logs, and compliance tracking systems to identify any gaps or process failures that led to the missed notifications. A comprehensive review of compliance across all relevant conditions</p> <p>will also be undertaken. Findings from the investigation will inform improvements to internal procedures and staff training, with the aim of preventing recurrence and strengthening future compliance efforts; and</p> <p>Continue to provide pre-construction notifications for all wind turbines and wind monitoring masts to CASA, Airservices Australia and the RAAF, in accordance with Condition B35.</p>	Noted. All pre-construction notifications for all wind turbines and wind monitoring masts to CASA, Airservices Australia and the RAAF have been made.	Closed



Finding ID	Compliance Requirement	Audit Recommendation	UWF Response	Proposed Due Date
OFI-1	Condition B16	Downer is recommended to: <ol style="list-style-type: none">1. Conduct maintenance, repair, or replacement of all degraded silt fences and sediment controls identified across the transmission tower alignment and around stockpiles.2. Reinstate controls to comply with the project's Erosion and Sediment Control Plan (ESCP) and Blue Book standards.	UWF will ensure all sediment and erosion controls are maintained in accordance with <i>Managing Urban Stormwater - Soils and Construction Volume 1 (Landcom, 2004)</i> and <i>Managing Urban Stormwater – Soils and Construction Volume 2C Unsealed Roads (DECC, 2008)</i> , or their latest versions;	Ongoing